Maryland Historical Trust

Maryland Inventory of Historic Properties number: M:15-94 Name: Howilands Mull Rd Over	Leveling Rever
The bridge referenced herein was inventoried by the Maryland State H Historic Bridge Inventory, and SHA provided the Trust with eligibility The Trust accepted the Historic Bridge Inventory on April 3, 2001. The determination of eligibility.	ghway Administration as part of the determinations in February 2001.
MARYLAND HISTORICAL TRI Eligibility RecommendedEligib	JST oility Not RecommendedX
Criteria:ABCD Considerations:AB	CDEFGNone
Criteria:ABCD Considerations:AB _ Comments:	CDEFGNone
	CDEFGNone Date:3 April 2001

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

SHA Bridge No. M 98 Name: Havilands Mill Road over Hawlings River

Location: Street/Road Name and Number: Havilands Mill Road
City/Town: Brookville Vicinity X
County: Montgomery
Ownership:State_X_County_MunicipalOther
This bridge projects over: _Road_Railway_X_Water_Land
Is the bridge located within a designated district: _yes X_no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
_Timber Bridge _Beam Bridge_Truss-Covered_Trestle _Timber-and-Concrete
_Stone Arch
_Metal Truss
_Movable BridgeSwing _Bascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
Metal GirderRolled GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
_Metal Suspension
_Metal Arch
_Metal Cantilever
X Concrete X Concrete Arch _Concrete Slab_Concrete Beam Rigid Frame
Other Type Name

Describe Setting:

Bridge M 98 carries Havilands Mill Road over Hawlings River in Montgomery County. Havilands Mill Road runs east and west over the northern flowing Hawlings River. The area immediately adjacent to the bridge has little residential development.

Describe Superstructure and Substructure:

Bridge M 98 is a single span filled concrete arch bridge. The length of the bridge is 43 feet, and it has a clear span measuring 39 feet 10 inches at the springline. The bridge has a rise of approximately 6 feet 7 inches from springline to crown. The rise to run ratio is 26 percent. The spandrel walls are approximately 12 feet in height. The wingwalls are approximately 10 feet by 8 feet. There is a clear roadway width of 16 feet 4 inches, with an overall bridge width of 17 feet 8 inches. The spandrel walls have heavy deterioration and large areas of patching. The walls exhibit efflorescence and reinforcement bar exposure. The abutments exhibit efflorescence and cracking. The arch ring has moderate to heavy cracking throughout the ring. The exterior of the arch ring on both the downstream and upstream sides have heavy scaling and reinforcement bar exposure. According to a 1997 inspection report, the bridge is in satisfactory condition, with a sufficiency rating of 67.9.

The parapets are not original. They are cast in place concrete barriers that measure 43 feet long and 3 feet tall. The parapets are heavily patched and exhibit heavy scaling.

Discuss Major Alterations:

At an unknown date the parapets were removed and replaced by cast in place concrete barriers.

When Built: circa 1920

Why Built: Improvement of lateral corridors

Who Built: State Roads Commission
Who Designed: State Roads Commission
Why Altered: To replace deteriorated parapets

Was this bridge built as part of an organized bridge building campaign? No, this bridge was not built during an organized bridge building campaign.

Surveyor Analysis:

This bridge may have NR significance for association with:

_A Events _Person _C Engineering/Architectural

This bridge was determined not eligible by the Interagency Review Committee in March 1996..

Was this bridge constructed in response to significant events in Maryland or local history?

In 1920 the Maryland State Legislature enacted the "Lateral and Post Roads Loan of 1920." The act that created this loan provided that the proceeds were to be used for the construction of rural post roads, lateral roads and the extension of the State Roads System, with the assistance of funds from the federal government and several counties in the State. Half of the loan was used for the purpose construction of lateral roads. This money was apportioned to the counties on the basis of actual road mileage. The counties then matched the State's money with bond issues, special assessments, or other revenue.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No this bridge is not located in an area that is eligible for historic designation.

Is the bridge a significant example of its type?

No, this bridge is not a significant example of its type. The loss of the original parapets and the present condition of the character defining element reduces the significance of the bridge.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Although this bridge's character defining elements are intact, they are in a deteriorated state. In addition, the parapets are not original.

Should this bridge be given further study before significance analysis is made and why?

No this bridge should not be given further study.

Bibliography:		
County inspection/bridge files	X	SHA inspection/bridge files
Other (list):		


Surveyor:

Name: Stacie Y. Webb Date: March 1996

Organization: State Highway Admin. Telephone: (410) 545-8559

Address: 707 N. Calvert Street Baltimore Maryland

Edited by P.A.C. Spero and Company, December, 1997.





Inventory	#	M:	15-	94
-----------	---	----	-----	----

Name M98 - HAVILANDS MILL ROOKER H County/State Montgomery Imp Name of Photographer FRANK JULIANO Date 295	RIVER
Location of Negative	
Description APPROACH WEST	
1 4	

Number 8 of 35



inventory # $\frac{m_2 t_3}{t_1}$
Name Ma8 - HAVILANDS MILLERO OVER HAWLING RIVE
County/State MONTGOMERY MD
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description ELEVATION SOUTH
Number 16 of 38
Number 10 of 20

Inventory # M. 15-94



Inventory # <u>M: 15-94</u>

Name M98 - HAVILANDS MILL RO OVER HAWLINGS RIVER County/State Montoomery / mo Name of Photographer FRANK JULIANO Date 295
Location of Negative SHP
Description ELEMNON WORTH
34 4
Number 9 of 35



Inventory # <u>M:15-94</u>

Name M98-HAULANDS MILLRO OVER HAWLINGS RIVER County/State Montgomery MD Name of Photographer FRANK JULIANO Date 295
Location of Negative
Description APPROACH EAST
4 4 Number 1 of 35